

# ROTARY HAMMER ID HDC03-26

Part No.: 26478

# **OPERATION INSTRUCTIONS**



Read though carefully and understand these instructions before use.

# **GENERAL SAFETY RULES**

# (For All Tools)

**WARNING!** Read and understand all instructions. Failure to follow all instructions listed below may result in electric shock, fire and/or serious personal injury.

#### **Work Area**

- Keep work area clean and well lit. Cluttered areas and benches invite injuries.
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases, or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep bystanders, children, and visitors away while operating a power tool. Distractions can cause you to lose control.

# **Electrical Safety**

- 4. Power tools must be plugged into an outlet properly installed or grounded in accordance with all codes and ordinances. Never modify the plug in any way. Do not use any adaptor plugs with grounded (earthed) power tools. The original plug and proper outlet may reduce the risk of electric shock.
- Avoid body contact with grounded surfaces such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is grounded.
- Do not expose power tools to rain or wet conditions. Water entering a power tool will increase the risk of electric shock.
- 7. Do not abuse the cord. Never use the cord to carry the tools or pull the plug from an outlet. Keep cord away from heat, oil, sharp edges or moving parts. Replace damaged cords immediately. Damaged or entangled cords increase the risk of electric shock.
- 8. When operating a power tool outside, use only extension cords intended for outdoors use. These cords may reduce the risk of electric shock.

# **Personal Safety**

- 9. Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use tool while tired or under the influence of drugs, alcohol, or medication. A moment of inattention while operating power tools may result in serious personal injury.
- 10. Dress properly. Do not wear loose clothing or jewelry. Contain long hair.

  Keep your hair, clothing, and gloves away from moving parts. Loose clothes, jewelry, or long hair can be caught in moving parts.
- 11. Avoid accidental starting. Be sure switch is off before plugging in. Carrying tools with your finger on the switch or plugging in tools that have the switch on invites accidents.
- 12. Remove adjusting keys or wrenches before turning the tool on. A wrench or a key that is left attached to a rotating part of the tool may result in personal injury.
- 13. **Do not overreach. Keep proper footing and balance at all times.** Proper footing and balance enables better control of the tool in unexpected situations.
- 14. **Use safety equipment. Always wear eye protection.** Dust mask, non-skid safety shoes, hard hat, or hearing protection must be used for appropriate conditions. Ordinary eye or sun glasses are NOT eye protection.
- 15. If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.

#### **Tool Use and Care**

- 16. **Do not force tool. Use the correct tool for your application.** The correct tool will do the job better and safer at the rate for which it is designed.
- 17. **Do not use tool if switch does not turn it on or off.** Any tool that cannot be controlled with the switch is dangerous and must be repaired.
- 18. Disconnect the plug from the power source before making any adjustments, changing accessories, or storing the tool. Such preventive safety measures reduce the risk of starting the tool accidentally.
- 19. Store idle tools out of reach of children and other untrained persons. Tools are dangerous in the hands of untrained users.

- Maintain tools with care. Keep cutting tools sharp and clean. Properly
  maintained tools with sharp cutting edges are less likely to bind and are
  easier to control.
- 21. Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tools operation. If damaged, have the tool serviced before using. Many accidents are caused by poorly maintained tools.
- 22. Use only accessories that are recommended by the manufacturer for your model. Accessories that may be suitable for one tool, may become hazardous when used on another tool.

#### Service

- 23. **Tool service must be performed only by qualified repair personnel.**Service or maintenance performed by unqualified personnel could result in a risk of injury.
- 24. When servicing a tool, use only identical replacement parts. Follow instructions in the Maintenance section of this manual. Use of unauthorized parts or failure to follow Maintenance instructions may create a risk of electric shock or injury.

#### **VOLTAGE WARNING:**

Before connecting the tool to a power source (receptacle, outlet, etc.), be sure the voltage supplied is the same as that specified on the nameplate of the tool. A power source with voltage greater than that specified for the tool can result in SERIOUS INJURY to the user, as well as damage to the tool. If in doubt, DO NOT PLUG IN THE TOOL. Using a power source with voltage less than nameplate rating is harmful to the motor.

# **SPECIFICATIONS**

Rated Power Input	750 W
Blows per Minute	3200 /min
No-Load Speed	500 /min
Max. Drilling Capacity (concrete)	Ø26 mm
Net Weight	5.0 kg

<sup>\*\*</sup>Due to the continuing program of research and development, the specifications herein are subject to change without prior notice.

# **ADDITIONAL SAFETY RULES**

- Wear a hard hat (safety helmet), safety glasses and/or face shield. Ordinary eye or sun glasses are NOT safety glasses. It is also highly recommended that you wear a dust mask and thickly padded gloves.
- 2. Wear ear protectors when using the tool for extended periods. Prolonged exposure to high intensity noise can cause hearing loss.
- 3. Hold tools by insulated gripping surfaces when performing an operation where the cutting tool may contact hidden wiring or its own cord. Contact with a "live" wire will make exposed metal parts of the tool "live" and shock the operator.
- 4. Check and ensure that the drill bit be correctly installed and secured before operation.
- Under normal operation, the tool is designed to produce vibration. The screws can come loose easily, causing a breakdown or accident. Check tightness of screws carefully before operation.
- 6. In cold weather or when the tool has not been used for a long time, let the tool warm up for a while by operating it under no load. This will loosen up the lubrication. Without proper warm-up, hammering operation is difficult.

- 7. Always be sure to have a firm footing. Wear safety belt when using this tool in high locations and ensue no one is below.
- 8. Hold the tool firmly by both hands and always use the auxiliary handle.
- 9. Keep hands away from the rotating parts.
- 10. Do not leave the tool running. Operate the tool only when hand-held.
- 11. Do not point the tool at any one in the area when operating. The bit could fly out and injure someone seriously.
- 12. Do not touch the bit or parts close to the bit immediately after operation; they may be extremely hot and could burn your skin.
- 13. Some material contains chemicals which may be toxic. Take caution to prevent dust inhalation and skin contact. Follow material supplier safety data.

### SAVE THESE INSTRUCTIONS.

**WARNING!** MISUSE or failure to follow the safety rules stated in this instruction manual may cause serious personal injury.

# INSTRUCTIONS FOR OPERATION


# **Installing or Removing Drill Bit**

#### CAUTION:

 Always be sure that the tool is switched OFF and unplugged before installing or removing the drill bit.

Clean the bit shank and smear it with bit grease before installation.

To install the drill bit (SDS-plus shank), fully pull back the slide grip and insert the drill bit as far as it will go while rotating. (**Fig. 1**)




By releasing the slide grip, the drill bit will be secured automatically.

To remove the SDS-plus drill bit, fully pull back and hold the slide grip and the drill bit can be removed

# **Installation of Dust Cup**

Attach a dust cup to collect dust or particles for easy operation when drilling holes upward.

Use the dust cup by attaching it to the drill bit as shown in **Fig. 2**. When using a bit which has big diameter, enlarge the center hole of the dust cup.




# **Switch Action**

#### CAUTION:

 Before plugging in the tool, always check to see that the trigger switch actuates properly and returns to the "OFF" position when released.

To start the tool, simply pull the trigger. Release the trigger to stop. (Fig. 3)



# **Drilling Operation**


#### CAUTION:

 There is a tremendous and sudden twisting force exerted on the tool/bit at the time of hole break-through, when the hole becomes clogged with chips and particles, or when striking reinforcing rods embedded in the concrete.  Always use the auxiliary handle and firmly hold the tool by both auxiliary handle and main handle during operations. Failure to do so may result in the loss of control of the tool and potentially severe injury.

Drilling operations can be made on concrete, tile and flagstone etc. by installing a drill bit.

Position the bit at the desired location for the hole, then pull the switch trigger. Do not force the tool. Light pressure gives best results. Keep the tool in position and prevent it from slipping away from the hole. (Fig. 4)

Do not apply more pressure when the



hole becomes clogged with chips or particles. Instead, run the tool at an idle, and then remove the bit partially from the hole. By repeating this several times, the hole will be cleaned out and normal drilling may be resumed.

# **Depth Gauge**


#### CAUTION:

 The depth gauge cannot be used at the position where he depth gauge strikes against the tool body.

The depth gauge enables the drilling depth to be set for convenient drilling holes of uniform depth.

Loosen the auxiliary handle, and insert the linear part of the depth gauge into the fitting hole of the handle holder from the chuck section side. (**Fig. 5**)

Move the depth gauge to the desired




# **Core Bit (for Light Load) (Optional Accessory)**


Large caliber holes and blind holes can be drilled by using a core bit (for light load). In this case, use optional accessories for core bits, such as a center pin and core bit shank, to realize more rational operation.


# Installing the Core Bit

#### **CAUTION:**

- Always be sure that the tool is switched OFF and unplugged before installing or removing the core bit.
- Before installing the core bit, lubricate the screw portion of the core bit shank for easily removing.
- Screw the core bit onto the core bit shank.
   (Fig. 6)
- Install the core bit shank to the rotary hammer (refer to the installation of SDS-plus drill bit). (Fig. 7)
- Insert the center pin into the guide plate until it reaches the extremity.
- 4) Fit in the guide plate by aligning its concaved portion with the core bit tip. When the position of the concave is shifted by turning the guide plate right or left, the guide plate never slips off even when the tool is used in a downward direction. (Fig. 8)








# Boring

#### **CAUTION:**

- Always be sure to disconnect the plug from the power supply receptacle before removing the center pin and guide plate.
- Insert the plug into a power supply receptacle.
- A spring is built in the center pin.
   By straightly and gently pressing it to the wall or floor surface, the entire surface of the core bit tip attains contact to start operating. (Fig. 9)




3) When boring about 5 mm (3/16") in depth, the hole position can be determined. Then remove the center pin and guide plate from the core bit and continue the boring operation.

Application of excessive force will not only expedite the work, but will deteriorate the tip edge of the drill bit, resulting in reduced service life of the tool.

# Removing the Core Bit

 Hold the tool (with the core bit inserted) upward and start it to repeat impact operation several times, the screw of core bit shank will be loosened for easily to remove. (Fig. 10)




2) Remove the core bit shank from Fig. 10 the tool, hold the core bit with one hand, and strongly strike the head of the hexagonal portion of the core bit shank with a hand hammer for several times, whereby the round head screw is loosened and the core bit can be removed.

# **Demolition Operation**

#### **CAUTION:**

 Change the operating model only when the tool is switched off.

To change the operating model for demolition, press the locking button and turn the operating mode selector switch to the position as shown in **Fig. 11**.



### Lubrication

#### **CAUTION:**

Always be sure that the tool is switched OFF and unplugged before lubricating.

Lubrication should be done to ensure proper use of the tool.

Replenish grease immediately when any grease is leaking from loosened screw. Further use of the tool despite the grease shortage may cause seizure to reduce the service life.

# **MAINTENANCE AND INSPECTION**

#### CAUTION:

• Always be sure that the tool is switched off and unplugged before attempting to perform inspection or maintenance.

# 1. Inspecting Drill Bits

Blunt drill bit or chisel will decrease the work efficiency and causes the motor be overloaded. Exchange or sharpen your drill bits when they become blunt.

# 2. Inspecting the Mounting Screws

Regularly inspect all mounting screws and ensure that they are properly tightened.

Should any of the screws be loose, retighten them immediately. Failure to do so could result in serious hazard.


#### 3. Maintenance of the Motor


The motor unit winding is the very "heart" of the power tool. Exercise due care to ensure the winding does not become damaged and /or wet with oil or water.

# 4. Inspecting and Replacing Carbon Brushes

Remove and check the carbon brushes regularly. Replace when they wear down to the limit mark (Fig.12). Keep the carbon brushes clean and free to slip in the holders. Both carbon brushes should be replaced at the same time. Use only identical carbon brushes.

Use a screwdriver to remove the brush holder caps. Take out the worn carbon brushes insert the new ones and secure the brush holder caps. (Fig. 13)






\*Damaged cord must be replaced by

a special cord purchased from authorized service center.

\*\* To maintain product SAFETY and RELIABILITY, repairs, any other maintenance or adjustment should be performed by authorized centers, always using original replacement parts.



# **EXPLANATION OF GENERAL VIEW**

1	Steel Ball 5/16' (7.94)	32	Circlip	
2	Flat Key B 3×3×16	33	Slide Grip Holder	
3	Cylinder	34	Slide Grip	
4	Compression Spring (37.5 $\times 3.5 \times 77$ )	35	Steel Ball 9/32' (7.14)	
5	Striker	36	Retainer Sleeve	
6	O Ring (19.4×3)	37	O Ring (19.8×2.1)	
7	Driven Spiral Bevel Gear	38	O Ring (11×1.9)	
8	O Ring (19≺3.1)	39	Impact Bolt	
9	Piston Pin (6×24.5)	41	Compression Spring $(32.7 \times 2.2 \times 69)$	
10	Piston	42	Gear Housing	
11	Connecting Rod Assembly	43	Trade Mark	
12	O Ring (55×2)	44	Spiral Bevel Gear Shaft	
13	Slide Bearing	45	Spacer Ring 15×20×4.3	
14	Operating Mode Selector Switch	46	Ball Bearing 6002ZZ	
15	Pan Head Screw M4×12(with Spring Washer)	47	Washer (14×20×0.5)	
20	O Ring (55×2)	48	Washer (14×35×2)	
21	Oil/Grease Cap	49	Clutch Plate	
22	Nameplate	50	Helical Gear	
23	Hex Socket Head Screw M5× 25(with Spring Washer and Flat Washer)	51	Belleville Spring	
24	Cylinder Case	52	Nut M10×0.75	
25	Oil Seal	53	Ball Bearing 627ZZ	
26	Roundwire Snap Ring 35	54	Crank Shaft	
27	Washer (45×54.8×1)	55	Flat Key B 4×4×10	
28	Ball Bearing 6907ZZ	56	Ball Bearing 6202VV	
29	Rubber Washer $(47 \times 55 \times 7)$	57	Spacer Ring	
30	Pipe	58	Shaft Sleeve	
31	Front Cap	59	Hex Socket Head Bolt M4 × 16(with Spring and Flat Washer)	

# **EXPLANATION OF GENERAL VIEW**

60	Helical Gear	83	Pan Head Tapping Screw ST4.2 ×16 (with Flat Washer)	
61	Circlip for Shaft 12	84	Strain Relief (Cord Clip)	
62	Ball Bearing 688ZZ	85	Capacitor	
63	Needle Bearing HK0810	86	Switch Trigger	
64	Gear Housing Cover	87	Trigger Switch	
65	Ball Bearing 6001VV	88	Right –Half Handle	
66	Armature Assembly	89	Pan Head Screw M5×25 (with Spring and Flat Washer)	
67	Baffle Plate	90	Pan Head Tapping Screw ST5×25	
68	Pan Hd. Tapping Screw ST5×63	91	Roundwire Snap Ring for Shaft 30	
69	Stator Assembly	93	Oil Seal	
70	Ball Bearing 608ZZ	94	Wire Assembly	
71	Motor Housing	95	Wire 60	
72	Hex Socket Head Bolt M5×50 (with Spring and Flat Washer)	96	Wire 295	
73	Carbon Brush Holder		Auxiliary Handle	
74	Carbon Brush		Bolt M8≺30	
75	Brush Holder Cap	861	Handle Holder	
76	Hex Socket Head Screw with Flat Point M5×8		Steel Band	
77	Rear Cover		Depth Gauge holder	
78	Pan Hd. Tapping Screw ST4.2×17	862	Dust Cap	
79	Pan Hd. Tapping Screw ST4.2×17	863	Plastic Carton	
80	Left-half Handle	864	Oiler	
81	Cord	865	Depth Gauge	
82	Cord Guard	866	O Ring 19×3.1 (2 PCS)	



# مطرقة الحفر ID HDC03-26

26478 :.الرقم

# تعليمات التشغيل



يرجى قراءة وفهم هذه التعليمات بعناية قبل التعليمات استخدامها .

تحذيرات السلامة العامة لأداة الكهربانية.

متوراً اقرأ جميع تحذيرات السلامة، وكل التعليمات. قد يؤدي عدم اتباع حميع التعليمات المذكورة أدناه إلى صدمة كهربانية و حريق /أو إصابة خطيرة.

احتفظ بكل التحذيرات والتعليمات لاستخدامها في المستقبل.

يشير مصطّلح "أداّةً كهرّ بانيةً" في التّحذير اتّ إلىّ أداة كهر بأنية تعمل بالكهرباء أو تعمل بالبطارية.

- 1) السلامة في مكان العمل
- a خافظ على منطقة العمل نظيفة ومضاءة جيدًا. تدعو المناطق المزدحمة أو
- المظلمة إلى رقوع حوادث. لا تقد بتشغيل الأدوات الكهربانية في أجواء قابلة للانفجار ، مثل وجود سوانل أو غازات أو غبار قابل للاشتعال. الأدوات الكهربانية تخلق شرارات قد تشعل الغبار أو الدخان.
- أبق الأطفال والمتجولين بعيداً أثناء استخدام الأداة الكهربانية. حيث يمكن أن تتسبب الانحرافات في ققدان السيطرة.
  - السلامة الكهربائية
- أ. يجب أن تتطأبق مقابس الأدوات الكهربائية مع المخرج. لا تعدل القابس بأي شكل من الأشكال لا تستخدم أي مقابس تحويل مع الادوات الكهربائية الأرضية. المقابس التي لم يتم تعديلها والصمامات المتطابقة ستقلل من خطر الصدة الكعربائية الكعربائية.
- تجنب اتصال الجسم بالأرض أو الأسطح الأرضية، مثل الأنابيب والإشعاعات والمنافذ والثلاجات. مناك خطر متزايد من الصدمة الكهربائية إذا كان جسمك ما الأرب.
- لا تُعرض الأدوات الكهربانية للمطر أو الرطوبة. سيؤدي دخول الماء إلى أداة كهربائية إلى زيادة خطر التعرض لصدمة كهربائية ..
- لا تسيء استخدام السلك تستخدم السلك أبدا لحمل أو سحب أو فصل الأداة الكهربائية الجقي السلك بعيدا عن الحرارة والزيت والحواف الحادة أو الأجزاء المتحركة الأسلك المتضررة أو المتشابكة تزيد من خطر الصدمة الكيزاء المتحركة.
- عند تشغيل أداة كهربانية في الهواء الطلق، استخدم سلك تمديد مناسب للاستخدام في الهواء الطلق. ستخدام سلك مناسب للاستخدام في الهواء الطلق بقلل من خطر الصندمة الكهربانية.
- إذا كان تشغيل أداة كهربائية في مكان رطب أمرًا لا مفر منه ، فاستخدم مصدرًا محميًا لجهاز التيار المتبقى (RCD). استخدام RCD يقال من خطر الصدمة الكهربائية.
  - 3) السلامة الشخصية
- a) كان يقطّأ، وانتبه لما تقطعه واستخدم الحس السليم عند تشغيل أداة كهربائية.
   لا تستخدم أداة كهربائية وانت متعب أو تحت
   تأثير المخدرات أو الكحول أو الأدوية. لحظة من عدم الإنتباء أثناء تشغيل الأدوات الكهربائية قد تؤدي إلى إصابة شخصية خطيرة.

- استخدم معدات الحماية الشخصية. احرص دائمًا على ارتداء واقي للعينين. وسوف تقلل المعدات الوقائية المستخدمة من الإصابات الشخصية في الظروف الطاسبة مثل قناع الغيار، والأحذية الوقائية ضد الانزلاق، والقيمات الصلبة أو حماية السمع.
- منع البدء غير المقصود. تأكد من أن المقتاح في وضعية إيقاف التشغيل قبل توصيله بمصدر الطاقة و / أو بطراية البطارية أو الثقاط الاداة أو حملها. إن حمل الأدرات الكيربائية بإصبياف على المقتاح أو أدرات كيربائية النشطة التي تحقوي على المقتاح بدعو إلى وقوح حوائث.
- هم ببازالة أي مفتاح ضبط أو المفتاح الإنجليزي قبل تشغيل الأداة الكهربانية.
   قد بيؤدي وجود مفتاح انجليزي أو مفتاح متصل بالجزء الدوار من الأداة الكهربانية ألى مفتاح متصل بالجزء الدوار من الأداة الكهربانية إلى حدوث إصابة شخصية.
- و) لا تتجاوز الحدود. حافظ على أقدامك و توازنك في جميع الأوقات. مذا يسمح بتحكم أفضل في الأداة الكبر بائية في الحالات غير المتوقعة.
- أرتدي ملابسك بشكل مناسب. لا ترتدي ملابس قضفاضة أو مجوه (ات.
   أبقي شعرك وملابسك و القفازات بعيداً عن الأجزاء المتحركة. يبكن أن تعلق المدرس الفضفاضة أو المجره (ات أو الشعر الطويل في الأجزاء المتحركة.
- g) إذا تم توفير أجهزة لتوصيل مرافق استخراج القبل وجمعه، فتاكد من توصيلها واستخدامها بشكل صحيح. استخدام جمع الغبار بمكن أن يقلل من المخاطر المرتبطة بالغبار
  - استخدام الأدوات الكهربانية ورعايتها
- (a) لا تضغط على الأداة الكهربانية. استخدم الأداة الكهربانية المناسبة لتطبيقك.
   الأداة الكهربائية المناسبة ستقوم بالعمل بشكل أفضل وأكثر أمانًا بالمعدل الذي تم تصميمها من أجله.
- لا تستخدم الأداة الكهربانية إذا لم يتم تشغيل المفتاح وإيقاف تشغيله. أي أداة كهربائية لا يمكن التحكم فيها بالمفتاح تعتبر خطيرة ويجب إصلاحها.
- ) قم بقصل القابس عن الأداة الكهربائية و از الة بطارية الأداة الكهربائية .
   قبل إجراء أي تعديلات أو تغيير الملحقات أو تخزين الأدوات الكهربائية .
   هذه التدابير الوقائية للسلامة تقلل من أخطار تشغيل الأداة الكهربائية عن طريق الخطأ .
- تخزين الأدوات الكهربانية العاطلة بعيدًا عن متناول الأطفال ولا تسمح للأشخاص الذين لا يعرفون الأداة الكهربانية أو هذه التعليمات بتشغيل الأداة الكهربانية. تعتبر الأدوات الكهربانية خطيرة في أبدي المستخدمين غير المد بن:
- صيلة الأدوات الكهربائية تحقق من عدم النواء أو ربط الأجزاء الشخركة، وكسر الأجزاء وأي عدالة أخرى قد تؤثر على عمل الأداة الكهربائية. في حللة التلف، قم بإصلاح الآداة الكهربائية قبل استخدامها . تحدث العديد من الحرائث بسبب سوء صيانة الأدرائ الكهربائية .

أبق أدوات القطع حادة ونظيفة. أدوات القطع التي يتم الاحتفاظ بها بشكل صحيح مع حواف حادة أقل عر ضة للالتصاق وأسهل

وفقًا لهذه التعليمات استخدم الأداة الكهربائية والملحقات وأجزاء الأدوات وما إلى ذلك ، مع مراعاة ظروف العمل والعمل الذي يتعين القيام به. قد يؤدي استخدام الأداة الكهر بائية لعمليات مختلفة عن تلك المخصصة لها إلى وضع

#### الخدمة (5

اطلب صيانة أداتك الكهربائية بواسطة فني إصلاح مؤهل باستخدام قطع غيار متطابقة فقط سيضمن نلك الحفاظ على سلامة أداة الكهر بائية.

### تحذيرات السلامة من المطرقة

- a) ارتدي واقى الأذن. قد يؤدي التعرض المطول للضوضاء عالية الكثافة إلى فقدان السمع.
- استخدم المقبض المساعد، إذا تم توفيره مع الأداة. يمكن أن يؤدي فقدان السيطرة إلى إصابة شخصية.
- احتفظ بالأدوات الكهربائية على أسطح عازلة للقبض، عند إجراء عملية قد تلامس فيها أداة القطع الأسلاك الخفية أو سلكها الخاص. قطع الملحقات التي تتصل بسلك "حيوي" قد يجعل أجز اء معدنية مفتوحة من الأداة الكهر بائية "حية" ويمكن أن يعطى العامل صدمة كهربائية.

# تحذيرات قابس الكهرباء في المملكة المتحدة:

المنتج الخاص بك مجهز بمغلق كهربائي معتمد في 1-1363 BS مع فيوز داخلي معتمد في BS 1362 .

إذا لم يكن المقبس مناسبًا لمقبسك ، فيجب إز الته وتثبيت مغلق مناسب في مكانه من قبل وكيل خدمة العملاء المعتمد. يجب أن يكون للمقبس البديل نفس تصنيف الفيوز مثل القابس الأصلى.

يجب التخلص من القابس المقطوع لتجنب خطر الصدمة المحتملة ويجب عدم إدخاله في مقبس التيار الكهربائي في أي مكان آخر.





لتقليل خطر الإصابة، يجب على المستخدم قراءة دليل الإستخدام





#### معلومات تقنية

750	W	مدخلات الطاقة المقدرة
3200	min/	تردد التأثير المقدر
500	min/	سرعة بدون حمولة
26	mm	اقصى عمق للحفر (الخرسانة)
5.0	mm	الوزن الصافي للألة

أداة من الفئة الثانية

بسبب رنامج البحث والتطوير المستمر، المواصفات هنا عرضة للتغيير دون إشعار مسبق.

#### تعليمات التشغيل

#### تركيب أو إزالة قطعة الحفر

كما هو موضح في الشكل، اضغط على المقبض المنزلق للظرف بالخلف، وأدخلَ لقَمة الحفر في اتجاه السهم، وأدر اللقمة ببطء إلى أعلى الفتحة المربعة لمقبض الشريحة، ثم أدخلها حتى النهاية. عندما يتم توصيل لقمة الحفر بإحكام، حرر المقبض المنزلق لإعادتها إلى موضعها الأصلي ويتم تثبيت لقمة الحفر.

عند إزالة اللقمة، اتبع الإجراءات العكسية المذكورة أعلاه.


إذا لم يدور ظرف تشاك بسبب تراكم الغبار، فيمكن تشحيم المقبض المنزلق.

تحذير: تأكد دائمًا من إيقاف تشغيل الأداة وفصلها قبل إزالة القطعة أو تثبيتها.



عند حفر الثقوب لأعلى (على سبيل المثال: السقف). استخدم كوب الغبار من خلال تثبيته على لقمة الحفر كما هو موضح في الشكل. عند استخدام لقمة ذات قطر كبير، قم بتكبير الفتحة المركزية لكوب الغبار.

قم بتركيب كوب الغبار لتجميع الغبار أو الجزيئات لسهولة التشغيل




عملية الحفر

يمكن للآلة المثبتة بواسطة لقمة الحفر أن تقوم بالحفر على الخرسانة والبلاط والحجر البلاطي وما إلى ذلك.

1. ضع اللقمة في المكان المرغوب للفتحة، ثم اضغط على المفتاح لبدء تشغيل الجهاز.

2. لا تضغط على الأداة الكهربائية. يعطى الضغط الخفيف أفضل


تحذير: هناك قوة التواء هائلة ومفاجئة تمارس على الأداة/الريشة في وقت اختراق الثقب، أو عندما يصبح الثقب مسدودًا بالرقائق والجزيئات، أو عند ضرب قضبان التسليح المدمجة في الخرسانة. استخدم دائمًا المقبض الإضافي وأمسك الأداة بقوة أثناء التشغيل. قد يؤدي عدم القيام بذلك إلى فقدان السيطرة على الأداة واحتمال حدوث إصابة خطيرة.



مقياس العمق

يظهر تركيب مقياس العمق في الشكل التالي. 1. قم بفك المقبض الإضافي، وأدخل مقياس العمق في فتحة التركيب من جانب قسم ظرف تشاك.

2. انقل مقياس العمق إلى العمق المطلوب وقم بتثبيته عن طريق تدوير المقبض المساعد.



عملية الإغلاق والتشغيل


لتشغيل الأداة، ببساطة اضغط على زر التشغيل. أطلق زر التوقف. تحذير: قبل توصيل الأداة ، تحقق دائمًا من أن مفاتيح التشغيل تعمل بشكل صحيح وتعود إلى وضعية "OFF" عند تحريره .

• لقمة أساسية (للحمل الخفيف)


يمكن حفر ثقوب ذات عيار كبير باستخدام لقمة أساسية (للحمل

1. تثبيت القطعة الأساسية


1) قم بربط اللقمة الأساسية على ساق اللقمة الأساسية كما هو موضح في الشكل الموجود على اليمين. تحدير: قبل تثبيت لقمة الحفر الأساسية، قم بتشحيم الجزء اللولبي من ساق لقمة الحفر الأساسية لإزالتها بسهولة.



2) قم بتثبيت ساق اللقمة الأساسية بالمطرقة الدوارة (راجع تركيب لقمة الحفر).



3) أدخل الدبوس المركزي في لوحة التوجيه حتى يصل إلى الطرف. 4) تناسب في لوحة الدليل. عند تدوير لوحة التوجيه إلى اليمين أو اليسار، لن تنزلق لوحة التوجيه أبدًا حتى عند استخدام الأداة في اتجاه إلى الأسفل.




لوحة دليل
 قمة اللقمة الأساسية
 دبوس التركيز
 قطعة الأساسية

2. التجويف

-. 1) أدخل الفيشة في مقبس مصدر الطاقة.


أي تم بناء زنبرك في الدبوس المركزي. من خلال الضغط عليه بشكل مستقيم ولطيف على الحانط أو سطح الأرض، يصل السطح الكمال لطرف اللقمة الأساسي إلى نقطة التلامس لبدء التشغيل.
3 عند الحفر بعمق حوالي 5 مم، يمكن تحديد الثقب. ثم قم بإزالة الدبوس المركزي ولوحة التوجيه من لقمة الحفر الأساسية واستمر في عملية الثقب.



3. إزالة القطعة الأساسية


 أمسك الأداة لأعلى وابدأ تشغيلها لتكرار عملية التأثير عدة مرات، وسيتم فك المسمار لسهولة إزالته.

) أو قم بازالة ساق اللقمة الأساسية من الأداة، وأمسك اللقمة الأساسية بيد واحدة، واضرب ساق اللقمة الأساسية بقوة بمطرقة يدوية لعدة مرات، حيث يتم فك المسمار ويمكن إزالة اللقمة الأساسية.



• عملية الهدم

لتغيير نموذج التشغيل للهدم ، اضغط على الزر و قم بتحويل مفتاح الاختيار إلى الموضع كما هو موضح في الشكل.



صيانة

تحذير: تأكد دائمًا من أن الأداة مغلقة ومفصولة قبل محاولة إجراء فحص أو صيانة. فحص قطع الحفر

سيقلل الحفرة الأعمق من كفاءة العمل ويسبب زيادة حمولة المحرك. قم بتبديل أو شحذ قطع الحفر الخاصة بك عندما تصبح غير حادة.

• فحص مسامير التثبيت

افحص بانتظام جميع مسامير التثبيت وتأكد من إحكام ربطها بشكل صحيح. إذا تم العثور على مفكك، فيجب ربطه مرة أخرى لمنع تسرب الشحوم أو وقوع حوادث أخرى.

#### • صيانة المحرك

إن لف وحدة المحرك هو قلب الأداة الكهربائية يجب توفير الرعاية اللازمة لضمان عدم تلف الملفوف أو الرطوبة بالزيت أو الماء.

استبدل فرشاة الكربون

فرشاة الكربون الجزء الضعيف. قم بإزالة وفحص فرش الكربون بانتظام. استبدلها عندما تتآكل حتى علامة الحد. حافظ على فرش الكربون نظيفة وخالية من الانزلاق في الحوامل. يجب استبدال الفرشاة الكربونية في نفس الوقت. إزالة غطاء الفرشاة باستخدام مفك المسامير، وإخراج شجرة الكربون المتآكلة واستبدالها بآخر جديد، ومن ثم تشديد غطاء الفرشاة بشكل جيد.

إذا كان استندال سلك الإمداد ضروريًا ، فيجب أن يتم ذلك من قبل الشركة المصنعة أو وكيله لتجنب خطر على السلامة.

# شرح النظرة العامة

		<u> </u>	
O حلقة علي شكل (1.9×11)	38	الكرة الفولانية 16/5 ′ (7.94)	1
عصا الاصطدام	39	مفتاح مسطح 16×3×3 B	2
الدوار (28.3 × 2.2 × 69)	41	سلندر	3
علبة التروس	42	الدوار الكبير (37.5×3.5×77)	4
حلقة خارجية (15×22×4.5)	45	مهاجم	5
غطاء الزيت (4×28×F22)	45A	O حلقة علي شكل (3×19.4)	6
حامل الكرات (6002ZZ(LFB	46	O حلقة علي شكل (3.1×19)	8
غسالة (0.5×20×14)	47	دبوس المكبس (٤٤.5×6)	9
الغسالة(14×25×2)	48	المكبس AL7075	10
لوحة المقبض	49	مجمع عصا الاتصال	11
العداد الكبير	50	( 55×2 حلقة على شكل (O	12
بيلفيل الدوار	51	المحامل المنزلقة (30 $ imes$ 47 $ imes$ 10)	13
صامولة M10×0.75	52	مفتاح تحديد الوضع	14
حامل الكرات(627ZZ(LFB	53	برغي رأس المقلاة المتقاطع 12×M4 (مع غسالات زنبركية)	15
عمود لا مركزي	54	O حلقة على شكل(2×38)	20
مفتاح مسطح 4×12	55	حامل لغطاء الزيت	21
حامل الكرات(6202VV(LFB	56	غطاء الزيت	21
حلقة خارجية 12.1×20×8	57	مسامير رأس غطاء المقابس السداسية المسمار يجمع مع غسالة الدوارة و غسالات العادية 25× M5	23
حاوية الاحتفاظ	58	كم اسطوانة	24
المسمار الرئيسي ذو رأس سداسي 16×M4 (مع الغسالة المسطحة والدوارة)	59	غطاء الزيت	25
ترس صغير	60	حلقة للعمود 35	26
حلقة للعمود 12	61	غسالة(45×54.8×1)	27
حامل الكرات(688ZZ(LFB	62	حامل الكراتLFB)6907-2RS)	28
حاملة الإبرة (HK0810(INA	63	غلاف مطاطي(47×55×7)	29
دعامة المحرك	64	موقع الأنابيب	30
حامل الكرات(6001 VV(LFB	65	غطاء أمامي	31
هیکل	66	حلقة التجنيب الخاصة	32
لوحة الحاجز	67	حامل غطاء القفل	33
مسمار ربط ملوّلَب ذو رأس بصليب غائر 63×ST5	68	مجمع غطاء القفل	34
الجزء الثابت	69	الكرة الفولاذية 32/9' (7.14)	35
حامل الكرات 608VV	70	كم التجنيب	36
غطاء المحرك	71	كم التجنيب (SDS) للتصدير	36
مسامير رأس غطاء المقابس السداسية المسمار يجمع مع غسالة الدوارة و غسالات العادية 50×M5	72	يا خاتم (2.1×19.8)	37

غسالة الورق	100A	غطاء حامل الفرشاة	73
مجمع المقبض الثانوي	861	فرشاة الكربون	74
غطاء الغبار	862	غطاء حامل الفرشاة	75
صندوق بلاستيكي	863	ربط المسمار	76
شحم المطرقة	864	الغطاء الخلفي	77
مقياس العمق	865	مسدس تقطيع رأس العجلة 17×ST4.2	78
مقبض مساعد (الخيط الداخلي M8)	1-861	سلك الطاقة	81
حامل مقياس العمق	2-861	حامي السلك	82
حامل المقبض	3-861	مسدس تقطيع رأس العجلة 16×ST4	83
المشبك	4-861	مخفف الضغط	84
مسمار 30×M8	5-861	مكثف 0.33µF	85
المقبض الأيسر والأيمن (بما في ذلك الأجزاء: 88/80)	T1	زر الإغلاق و التشغيل	86
مجموعة الترس (بما في ذلك الأجزاء: 44/7)	T2	التشغيل والإيقاف	87
		مسمار ربط برأس صليبة 25×M5 (مع الغسالة المسطحة والدوارة)	89
		ممسمار ربط ملوّلب ذو رأس بصليب غائر .25×ST5	90
		حلقة للعمود 30	91
		حامل السلك (TY-DJ-10-1)	92
		عازل الدهون	93
		مجمع المحاثة	94
		سلك الرصاص 60	95
		سلك الرصاص 295	96

