


ID MS305N

Part No: 30364

MITRE SAW



Read though carefully and understand these instructions before use.

OPERATION INSTRUCTIONS

SAFETY RULES

Note: Failure to abide by these rules may cause serious injury to the user.

1. **Read Instructions:** Before operation, please read all instructions. Understand the tool's proper usage and potential hazards for your safety.
2. **Safety Guards:** Use all safety covers and follow standard operating procedures.
3. **Eye Protection:** Always wear safety glasses during operation.
4. **Grounding:** The tool must be properly grounded. If equipped with a 3-prong plug, it must be plugged into a matching 3-way grounded outlet.
5. **Remove Adjustment Keys:** Before starting the tool, always confirm that all wrenches and adjustment keys have been removed.
6. **Clean Workspace:** Keep the work area clean and organized. Cluttered areas and benches invite accidents.
7. **Environment:** Do not use tools in dangerous conditions. Do not expose tools to rain or wet environments. Ensure the work area is well-lit.
8. **Keep Bystanders Away:** Keep children and visitors at a safe distance from the work area.
9. **Child-Proof the Workshop:** Use padlocks, master switches, or remove starter keys to prevent unauthorized use by children.
10. **Do Not Force Tool:** The tool will perform better and safer when used at the speed for which it was designed.
11. **Use the Right Tool:** Do not force a small tool or attachment to do the job of a heavy-duty tool.
12. **Proper Apparel:** Do not wear loose clothing, gloves, or jewelry that can get caught in moving parts. Wear non-slip footwear and a protective hair covering for long hair.
13. **Dust Protection:** Always use safety glasses. If the operation creates significant dust or wood shavings, wear a dust mask or respirator.
14. **Secure the Workpiece:** Use clamps or a vise to hold the workpiece. This is significantly safer than using your hands and allows for two-handed operation of the tool.
15. **Proper Stance:** Do not overreach across the tool during operation. Maintain a stable, balanced position at all times.
16. **Tool Maintenance:** Keep tools sharp and clean for the best and safest performance. Follow the standard instructions for lubricating and changing accessories.
17. **Disconnect Power:** Always disconnect the power source before performing maintenance, such as changing blades, bits, or other attachments.
18. **Use Recommended Accessories:** Only use attachments recommended by the manufacturer. Using incorrect accessories may result in personal injury.
19. **Prevent Accidental Starting:** Ensure the power switch is in the "OFF" position before plugging the tool into a power source.

20. **Secure Storage:** Never leave a tool unattended while it is running or in a position where it could be knocked over. Serious injury could occur if the tool falls or starts unexpectedly.
21. **Inspect Damaged Parts:** Before further use, check all guards and parts for damage. Ensure they will operate properly and perform their intended function. Damaged parts should be properly repaired or replaced.
22. **Feed Direction:** Always feed the workpiece into a blade or cutter against the direction of rotation to ensure control and safety.
23. **Do Not Leave Tool Running:** Never leave the tool until it has come to a complete stop and the power has been disconnected.
24. **Drugs and Alcohol:** Do not operate any power tool while under the influence of drugs, alcohol, or medication that may impair your judgment or reflexes.
25. **Motor Maintenance:** When servicing or reconnecting the motor, ensure the power cord is completely disconnected from the electrical outlet.
26. **Warning (Respiratory Health):** Dust created by certain wood products can be harmful to your health. Always operate the tool in a well-ventilated area and use a dust collection system or a respiratory mask when necessary.

ADDITIONAL SAFETY RULES FOR MITRE SAW


1. **Assembly Warning:** Do not operate the tool until it has been fully assembled and mounted according to the provided instructions.
2. **Professional Guidance:** If you are unfamiliar with the operation of this machine, seek guidance from a supervisor, master technician, or a qualified professional.
3. **Personal Protective Equipment (PPE):** Always wear safety glasses, a face shield, or a surgical mask. Use full body protection, including safety shoes, tight-fitting long sleeves, and heavy-duty gloves.
4. **Approved Wheels Only:** Only use reinforced emery wheels equipped with a proper buffer.
5. **Secure Fasteners:** Before operation, ensure the axle screw and all workpiece clamps are securely tightened.
6. **Spindle Lock:** Before starting the machine, ensure the axis/spindle lock is released (OFF).
7. **Guard Usage:** Always keep the safety shield in place and follow standard operating procedures.
8. **Contact Warning:** Never touch the cutting disc with your hands.
9. **Secure Workpiece:** To prevent the workpiece from shifting, ensure it is fixed firmly in place before cutting.
10. **Two-Handed Operation:** Always operate the tool using both hands while cutting to maintain maximum control.
11. **Safety Zone:** Do not reach your hand across, under, or behind the cutting disc at any time.
12. **Complete Stop:** Before moving the workpiece or adjusting its angle, wait for the cutting disc to come to a complete stop.
13. **Flange Maintenance:** Ensure the inner surface of the disc flange and both sides of the disc are clean and free of debris.
14. **Mounting the Disc:** Carefully tighten the spindle screw. Avoid over-tightening, as this may damage the cutting disc or its flange.

15. **Speed Rating:** Only use cutting discs with a rated speed of at least 3900 RPM.
16. **Pre-Operation Inspection:** Before each use, check the cutting disc for cracks or any signs of damage. Replace a damaged or cracked disc immediately.
17. **Approved Flanges:** Use only the specifically defined and provided disc flanges for this tool.
18. **Start-Up Clearance:** Ensure the cutting disc is not in contact with the workpiece before turning on the power switch.
19. **Full Speed Operation:** Allow the motor to reach full-speed revolution before beginning an cut.
20. **Smooth Cutting:** After switching the tool on, lower the cutting disc gently until it touches the workpiece. Do not allow the disc to shake or jump, as this can damage the edge of the workpiece or shatter the disc.
21. **Optimized Pressure:** The tool is designed to cut efficiently with minimal downward pressure.
22. **Disc Wear:** Cutting performance and disc life vary based on usage. While rapid cutting is efficient, it may cause accelerated disc wear; however, it can help reduce burrs and heat-induced discolouration.
23. **Safety Shield:** Ensure the disc shield is in place and properly adjusted at all times.
24. **Explosion Hazard:** Do not operate the tool in the presence of flammable liquids, gases, or explosive atmospheres.
25. **Electrical Safety:** To avoid electric shock, do not operate the tool in wet locations or expose it to rain.
26. **Material Limitation:** This tool is specifically designed for cutting iron and steel. Do not use it for cutting wood, brick, aluminum, or magnesium.
27. **New Disc Calibration:** When mounting a new disc, do not stand directly in line with the disc when starting the tool. Run the tool for one minute as a safety check before beginning work.
28. **Power Isolation:** Always disconnect the plug from the power receptacle before performing any maintenance, adjustments, or accessory changes.
29. **Component Integrity:** If any part or component of the tool is missing or damaged, immediately disconnect the power source. Replace the faulty parts before resuming operation.

SPECIFICATIONS

MODEL	ID MS305N
Net Weight	15.5Kg
Rated Power Input	1800W
Rated Voltage	220-240V
Rated Frequency	50/60Hz
No-load Speed	4000r/min
Max. Blade Diameter	305mm
Bore Diameter	25.4/30mm
Bevel Cutting Angle	0-45°

EXPLODED VIEW FOR ID MS305N




SPARE PART LIST


No.	Part Name	Qty.	No.	Part Name	Qty.
1	Nut M10	1	41	Oil seal	1
2	Base	1	42	Pin	1
3	Bolt M6X35	1	43	Limited Outer	1
4	Fence	1	44	Spring Washer Φ18xΦ13.5	1
5	Active Fence	1	45	Screw	1
6	Press Block	1	46	Washer Φ17xΦ11x1.5	2
7	Hexagon nut M6	1	47	Washer Φ15xΦ10	1
8	Lock Wrench	1	48	Washer Φ16xΦ8x1	2
9	Washer Φ18xΦ6x1.5	1	49	Nut M8	1
10	Nut M6	2	50	Triadius wheel	1
11	Washer Φ20xΦ8x2	4	51	Rocker Arm Pin	1
12	Spring Washer 8	5	52	Washer A	1
13	Screw M8X25	5	53	Big Spring	1
14	Screw M5X50	1	54	Connection	1
15	Washer Φ10xΦ5x0.5	26	55	Rivet Φ2.5*5	2
16	Trigger	1	56	Scale	1
17	Spring Washer	1	57	Dust Cover	1
18	Screw M5X16	7	58	Screw M5X12	10
19	Washer	1	59	Rocker Arm	1
20	Nut M5	2	60	Screw M5X16	2
21	Washer 5	25	61	Wearing Plate	1
22	Trigger Housing	1	62	Washer Φ30xΦ17x2	2
23	Angle lock handle cap	1	63	Nut M16	1
24	Angle Lock handle	1	64	Washer 5	1
24.1	Bolt	1	65	Wrench	1
25	Angle lock handle cushions	1	66	Cable Armor	1
26	Washer Φ20xΦ10x2	4	67	Cable	1
27	Nut	1	68	Cable clamp	1
28	Angle lable	1	69	Screw ST4X14	2
29	Rotation plate	1	70	Internal wire clamp	
30	Screw M5X10	5	71	Handle top cover	1
31	Slotted plate	1	72	Handle cap	1
32	Washer Φ8xΦ4x0.5	6	73	Handle	1
33	Screw M4X10	6	74	Screw ST5X30	2
34	Washer Φ18xΦ12	2	75	Screw ST4X28	2
35	Screw M10X25	1	76	Screw M5X35	2
36	Shake direction	1	77	Lock on switch	1
37	Nut M8	3	78	Switch button	1
38	Bolt M8X30	2	79	Brush wire	1
39	Bolt M8X40	1	80	Switch	1
40	Pin Cap	1	81	Spring of Lock	1

SPARE PART LIST

No.	Part Name	Qty.	No.	Part Name	Qty.
82	Spring of Button	1	123	Gear	1
83	Handle bottom cap	1	124	Spring Washer 16	1
84	Screw ST4X22	6	125	Bearing 6000	1
85	Wool Felt Ring	1	126	Connect	1
86	Spring	1	127	Screw	1
87	Pin	1	128	Screw M6x16	1
88	Hatch Washer 6	1	129	Guard scale board	1
89	Lock Button	1	130	Screw 5*8	3
90	Fan guide	1	131	Bearing Clip 4.7	1
91	Bearing 6202	1	132	Wheel	1
92	Rotor	1	133	Circle	1
93	Bearing 6001	1	134	Protection Cover	1
94	Washer Φ27xΦ21	1	135	Vise clamp	1
95	Stator	1	136	Lead screw	1
96	Screw ST5X65	2	137	Handle	1
97	Housing	1	138	Screw M6×20	1
98	Screw M5X25	4	139	Connect Pole	1
99	Brush Holder	2	140	Stand Bar	1
100	Carbon Brush	2	141	Socket-Wrench	1
101	Cap of Brush Holder	2	142	Steel Wire	1
102	Washer 4	2	143	Dust Bag	1
103	Screw M4X12	2	144	Screw ST4X14	3
104	Rear Cover	1	145	Screw ST4X12	2
105	Guard spring	1			
106	Screw M6X12	2			
107	Guard plate	1			
108	Washer Φ12xΦ6x1	1			
109	Guard circle	1			
110	Bolt M8	1			
111	Flange	1			
112	Blade Washer	1			
113	Blade	1			
114	Flange	1			
115	Bearing Holder	1			
116	Cap of Bear holder	1			
117	Bearing 6203	1			
118	Spindle	1			
119	Steel Ball Φ5	1			
120	Key A5X16	1			
121	Flat circle	1			
122	Spring Washer 20	1			



www.idealpowertools.com




قائمة قطع الغيار

رقم	اسم الجزء	كمية	رقم	اسم الجزء	كمية
82	نابض الزر	1	123	الترس	1
83	غطاء المقيض السفلي	1	124	غشالة زنبركية ١٦	1
84	ST4×22 برغي	1	125	رولمان بلي ٦٠٠٠	1
85	حلقة لباد	1	126	وصلة	1
86	نابض	1	127	برغي	1
87	نبوس	1	128	M6×16 برغي	1
88	غشالة قفل ٦	1	129	لوحة تدرج الواقي	1
89	زر القفل	1	130	برغي ٨×٥	3
90	موجة المروحة	1	131	مشبك رولمان ٤,٧	1
91	رولمان بلي ٦٢٠٢	2	132	عجلة	1
92	الدوار	4	133	حلقة	1
93	رولمان بلي ٦٠٠١	5	134	غطاء الحماية	1
94	Φ27×Φ21 غشالة	5	135	ملزمة	1
95	المعوض الثابت	1	136	قضيب لولبي	1
96	ST5×65 برغي	26	137	مقيض	1
97	الهيكل	1	138	M6×20 برغي	1
98	M5×25 برغي	1	139	عمود التوصيل	1
99	حامل الفرشاة	7	140	قضيب الوقوف	1
100	فرشاة كربونية	1	141	مفتاح مقيس	1
101	غطاء حامل الفرشاة	2	142	سلك فولادي	1
102	غشالة ٤	25	143	كيس الغبار	1
103	M4×12 برغي	1	144	ST4×14 برغي	3
104	الغطاء الخلفي	1	145	ST4×12 برغي	2
105	نابض الواقي	1			
106	M6×12 برغي	1			
107	لوحة الواقي	1			
108	Φ12×Φ6×1 غشالة	4			
109	حلقة الواقي	1			
110	M8 مسمار	1			
111	الفلانج	1			
112	غشالة الشفرة	5			
113	الشفرة	1			
114	الفلانج	6			
115	حامل الرولمان	6			
116	غطاء حامل الرولمان	2			
117	رولمان بلي ٦٢٠٣	1			
118	(Spindle) العمود	1			
119	Φ5 كرة فولادية	3			
120	A5×16 مفتاح	2			
121	حلقة مسطحة	1			
122	غشالة زنبركية ٢٠ #	1			

قائمة قطع الغيار

رقم	اسم الجزء	كمية	رقم	اسم الجزء	كمية
1	M10صامولة	1	41	ختم زيت	1
2	القاعدة	1	42	ديوس	1
3	M6×35مسمار	1	43	الحذ الخارجي	1
4	السياج	1	44	Φ18×Φ13,5 غشالة زنبركية	1
5	السياج المتحرك	1	45	برغي	1
6	كتلة الضغط	1	46	Φ17×Φ11×1,5 غشالة	2
7	M6صامولة منداسية	1	47	Φ15×Φ10 غشالة	1
8	مفتاح القفل	1	48	Φ16×Φ8×1 غشالة	2
9	Φ18×Φ6×1,5 غشالة	1	49	M8صامولة	1
10	M6صامولة	2	50	عجلة ثلاثية	1
11	Φ20×Φ8×2 غشالة	4	51	ديوس ذراع التارجح	1
12	غشالة زنبركية ٨	5	52	A غشالة	1
13	M8×25برغي	5	53	نايض كبير	1
14	M5×50برغي	1	54	وصلة	1
15	Φ10×Φ5×0,5 غشالة	26	55	Φ2,5×5 مسمار برشام	2
16	الزناد	1	56	ميزان (لتدريج)	1
17	غشالة زنبركية	1	57	غطاء غبار	1
18	M5×16برغي	7	58	M5×12برغي	10
19	غشالة	1	59	ذراع التارجح	1
20	M5صامولة	2	60	M5×16برغي	2
21	غشالة ٥	25	61	لوحة احتكاك	1
22	هيكل الزناد	1	62	Φ30×Φ17×2 غشالة	2
23	غطاء مقبض قفل الزاوية	1	63	M16صامولة	1
24	مقبض قفل الزاوية	1	64	غشالة ٥	1
24,1	مسمار	1	65	مفتاح	1
25	وسائد مقبض قفل الزاوية	1	66	درع الكابل	1
26	Φ20×Φ10×2 غشالة	4	67	الكابل	1
27	صامولة	1	68	مشبك الكابل	1
28	ملصق الزاوية	1	69	ST4×14برغي	2
29	لوحة الدوران	1	70	مشبك السلك الداخلي	1
30	M5×10برغي	5	71	غطاء المقبض العلوي	1
31	لوحة مشقوقة	1	72	غطاء المقبض	1
32	Φ8×Φ4×0,5 غشالة	6	73	المقبض	1
33	M4×10برغي	6	74	ST5×30برغي	2
34	Φ18×Φ12 غشالة	2	75	ST4×28برغي	2
35	M10×25برغي	1	76	M5×35برغي	2
36	اتجاه الاهزاز	1	77	زر تثبيت التشغيل	1
37	M8صامولة	3	78	زر التشغيل	1
38	M8×30مسمار	2	79	سلك الفرشاة	1
39	M8×40مسمار	1	80	المفتاح	1
40	غطاء الديوس	1	81	نايض القفل	1



١٦. فحص ما قبل التشغيل: قبل كل استخدام، افحص قرص القطع للتأكد من عدم وجود تشققات أو علامات تلف. استبدل أي قرص متشقّق أو تالف فوراً.
١٧. الفلانجات المعتمدة: استخدم فقط الفلانجات المحددة والمزوّدة مع هذه الأداة.
١٨. خلو منطقة التشغيل: تأكد من أن قرص القطع غير ملامس لقطعة العمل قبل تشغيل مفتاح الطاقة.
١٩. الوصول للسرعة الكاملة: اترك المحرك يصل إلى سرعة الدوران الكاملة قبل بدء القطع.
٢٠. القطع السلس: بعد تشغيل الأداة، اخفض قرص القطع برفق حتى يلامس قطعة العمل. لا تسمح للقرص بالاهتزاز أو القفز، فقد يؤدي ذلك إلى تلف حافة قطعة العمل أو تكسير القرص.
٢١. الضغط المثالي: تم تصميم الأداة للقطع بكفاءة باستخدام ضغط خفيف للأسفل فقط.
٢٢. تآكل القرص: تختلف كفاءة القطع وعمر القرص حسب الاستخدام. قد يؤدي القطع السريع إلى تآكل أسرع للقرص، لكنه يساعد في تقليل التآكل وتغيّر اللون الناتج عن الحرارة.
٢٣. درع الحماية: تأكد من أن درع القرص في مكانه ومضبوط بشكل صحيح في جميع الأوقات.
٢٤. خطر الانفجار: لا تشغّل الأداة بالقرب من السوائل أو الغازات القابلة للاشتعال أو في بيئات قد تحتوي على أبخرة متفجرة.
٢٥. السلامة الكهربائية: لتجنب الصعق الكهربائي، لا تشغّل الأداة في أماكن رطبة ولا تعرّضها للمطر.
٢٦. حدود المواد: تم تصميم هذه الأداة خصيصاً لقطع الحديد والصلب. لا تستخدمها لقطع الخشب أو الطوب أو الألومنيوم أو المغنيسيوم.
٢٧. معايرة القرص الجديد: عند تركيب قرص جديد، لا تقف مباشرة في خط القرص عند تشغيل الأداة. دع الأداة تعمل لمدة دقيقة واحدة كاختبار أمان قبل البدء بالعمل.
٢٨. عزل الطاقة: افصل القابس عن مصدر الكهرباء دائماً قبل إجراء أي صيانة أو تعديلات أو تغيير للملحقات.
٢٩. سلامة المكونات: إذا كان أي جزء من الأداة مفقوداً أو تالفاً، افصل مصدر الطاقة فوراً. استبدل الأجزاء التالفة قبل استئناف التشغيل.

تحديد

ID MS305N	الطراز
١٥,٥ كجم	الوزن الصافي
١٨٠٠ واط	قدرة الإدخال المقننة
٢٢٠-٢٤٠ فولت	الجهد المقنّن
٥٠/٦٠ هرتز	التردد المقنّن
٤٠٠٠ دورة/دقيقة	سرعة الدوران بدون حمل
٣٠٥ مم	القطر الأقصى للشفرة
٢٥,٤/٣٠ مم	قطر الثقب
٥٤٥-٥٠	زاوية القطع المائلة


٢٠. **التخزين الآمن:** لا تترك الأداة دون مراقبة أثناء تشغيلها أو في وضع قد تتعرض فيه للسقوط. قد تحدث إصابات خطيرة إذا سقطت الأداة أو بدأت العمل بشكل غير متوقع.
٢١. **فحص الأجزاء التالفة:** قبل الاستخدام مرة أخرى، افحص جميع الوافيات والأجزاء للتأكد من عدم وجود تلف. تأكد من أنها تعمل بشكل صحيح وتؤدي وظيفتها المقصودة. يجب إصلاح الأجزاء التالفة أو استبدالها بشكل مناسب.
٢٢. **اتجاه التغذية:** أدخل قطعة العمل دائماً باتجاه الشفرة أو القاطع عكس اتجاه الدوران لضمان التحكم والسلامة.
٢٣. **عدم ترك الأداة تعمل:** لا تترك الأداة وهي تعمل. انتظر حتى تتوقف تماماً عن الدوران ويتم فصل مصدر الطاقة.
٢٤. **الأدوية والكحول:** لا تشغل أي أداة كهربائية تحت تأثير المخدرات أو الكحول أو الأدوية التي قد تؤثر على حكمك أو ردود فعلك.
٢٥. **صيانة المحرك:** عند صيانة المحرك أو إعادة توصيله، تأكد من فصل سلك الطاقة بالكامل عن المقبس الكهربائي.
٢٦. **تحذير (الصحة التنفسية):** الغبار الناتج عن بعض أنواع الأخشاب قد يكون ضاراً بالصحة. شغل الأداة دائماً في مكان جيد التهوية، واستخدم نظام شط الغبار أو قناعاً تنفسياً عند الضرورة.

قواعد سلامة إضافية لمنشأ الميتر


١. **تحذير التجميع:** لا تشغل الأداة قبل تجميعها وتثبيتها بالكامل وفقاً للتعليمات المرفقة.
٢. **الإشراف المهني:** إذا لم تكن على دراية بطريقة تشغيل هذه الآلة، فاطلب الإرشاد من مشرف أو فني محترف أو شخص مؤهل.
٣. **معدات الحماية الشخصية:** ارتد دائماً نظارات السلامة أو درع الوجه أو كمامة جراحية. استخدم حماية كاملة للجسم، بما في ذلك أحذية السلامة، وملابس طويلة ضيقة، وقفازات قوية.
٤. **العجلات المعتمدة فقط:** استخدم فقط عجلات الصنفرة المقواة والمزودة بوسادة حماية مناسبة.
٥. **تثبيت المشابك:** قبل التشغيل، تأكد من إحكام ربط مسمار المحور وجميع مشابك تثبيت قطعة العمل.
٦. **قفل المحور:** قبل تشغيل الآلة، تأكد من أن قفل المحور/العمود في وضع الإيقاف.
٧. **استخدام الواقي:** حافظ دائماً على وجود درع الحماية في مكانه، واتبع إجراءات التشغيل القياسية.
٨. **تحذير اللمس:** لا تلمس قرص القطع بيدك مطلقاً.
٩. **تثبيت قطعة العمل:** لمنع انزلاق قطعة العمل، تأكد من تثبيتها بإحكام قبل البدء بالقطع.
١٠. **التشغيل باليدين معاً:** شغل الأداة دائماً بكلتا اليدين أثناء القطع لضمان أقصى قدر من التحكم.
١١. **منطقة الأمان:** لا تمد يدك فوق أو تحت أو خلف قرص القطع في أي وقت.
١٢. **التوقف الكامل:** قبل تحريك قطعة العمل أو تعديل زاويتها، انتظر حتى يتوقف قرص القطع تماماً.
١٣. **صيانة الفلانج:** تأكد من أن السطح الداخلي لفلانج القرص وجانبي القرص نظيفان وخاليان من الأتربة.
١٤. **تركيب القرص:** قم بشد مسمار المحور بعناية. تجنب الشد الزائد، فقد يؤدي ذلك إلى تلف قرص القطع أو الفلانج.
١٥. **تصنيف السرعة:** استخدم فقط أقراص القطع ذات سرعة مصنفة لا تقل عن ٣٩٠٠ دورة/دقيقة.

ملاحظة: عدم الالتزام بهذه القواعد قد يؤدي إلى إصابات خطيرة للمستخدم.

١. **قراءة التعليمات:** قبل التشغيل، يُرجى قراءة جميع التعليمات. افهم الاستخدام الصحيح للأداة والمخاطر المحتملة لضمان سلامتك.
٢. **واقبات السلامة:** استخدم جميع أغطية الحماية واتبع إجراءات التشغيل القياسية.
٣. **حماية العين:** ارتد دائمًا نظارات السلامة أثناء التشغيل.
٤. **التأريض:** يجب تأريض الأداة بشكل صحيح. إذا كانت مزودة بقابس ثلاثي السنون، فيجب توصيلها بمقبس أرضي ثلاثي متوافق.
٥. **إزالة مفاتيح الضبط:** قبل تشغيل الأداة، تأكد دائمًا من إزالة جميع المفاتيح ومفاتيح الضبط.
٦. **نظافة منطقة العمل:** حافظ على منطقة العمل نظيفة ومنظمة. الفوضى على الطاولات أو الأرضيات قد تسبب الحوادث.
٧. **البيئة:** لا تستخدم الأدوات في ظروف خطيرة. لا تعرض الأدوات للمطر أو البيئات الرطبة. تأكد من أن منطقة العمل مضاءة جيدًا.
٨. **إبعاد المتواجدين:** أبق الأطفال والزوار على مسافة آمنة من منطقة العمل.
٩. **تأمين الورشة:** استخدم الأقفال أو المفاتيح الرئيسية أو أزل مفاتيح التشغيل لمنع الاستخدام غير المصرح به من قبل الأطفال.
١٠. **عدم إجبار الأداة:** ستعمل الأداة بشكل أفضل وأكثر أمانًا عند استخدامها بالسرعة المصممة لها.
١١. **استخدام الأداة المناسبة:** لا تجبر أداة صغيرة أو ملحقة صغيرة على أداء عمل يتطلب أداة قوية.
١٢. **الملابس المناسبة:** تجنب ارتداء الملابس الفضفاضة أو القفازات أو المجوهرات التي قد تعلق بالأجزاء المتحركة. ارتد أذنية غير قابلة للانزلاق وغطاء شعر واقٍ للشعر الطويل.
١٣. **الحماية من الغبار:** استخدم نظارات السلامة دائمًا. وإذا نتج عن التشغيل غبار كثيف أو نشارة خشب، ارتد قناع غبار أو جهاز تنفس.
١٤. **تثبيت قطعة العمل:** استخدم المشابك أو المِلْزِمة لتثبيت قطعة العمل. هذا أكثر أمانًا بكثير من استخدام اليدين ويسمح بالتحكم بالأداة بكلتا اليدين.
١٥. **وضعية الجسم الصحيحة:** لا تمد جسمك فوق الأداة أثناء التشغيل. حافظ على وضعية ثابتة ومتوازنة في جميع الأوقات.
١٦. **صيانة الأداة:** حافظ على الأدوات حادة ونظيفة للحصول على أفضل أداء وأكثر أمانًا. اتبع التعليمات القياسية للتشحيم وتغيير الملحقات.
١٧. **فصل الطاقة:** فصل مصدر الطاقة دائمًا قبل إجراء أي صيانة، مثل تغيير الشفرات أو الرووس أو الملحقات الأخرى.
١٨. **استخدام الملحقات الموصى بها:** استخدم فقط الملحقات الموصى بها من الشركة المصنعة. استخدام ملحقات غير مناسبة قد يؤدي إلى إصابة شخصية.
١٩. **منع التشغيل غير المقصود:** تأكد من أن مفتاح التشغيل في وضع "إيقاف" قبل توصيل الأداة بمصدر الطاقة.



رأى ميتري ID MS305N الجزء رقم: ٣.٣٦٤



اقرأ هذه التعليمات بعناية وفهمها قبل الاستخدام. □

تعليمات التشغيل